

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 4A




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9

$R = 200 \text{ to } 800 \text{ ohm}$
 $R_1 = 20 \text{ to } 80 \text{ ohm}$
 $C = .1\mu\text{f} \text{ to } 5\mu\text{f}$




FIG. 10




FIG. 11




FIG. 12




FIG. 13

FIG. 14

